

# Work Order ID 74038

Tuesday, September 20, 2011 3:45:44 PM



Page 1

Item ID: D2856-400-720

Accept



Setup Start



Revision ID:

Stop



Item Name: Abrasion Strip

Start Date: 9/20/2011 Start Qty: 30.00



Cust Item ID:

Required Date: 9/21/2011 Req'd Qty: 30.00



Customer:

Reference:

Approvals:

Process Plan:

*[Signature]*

Date: 11-09-20

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

D2856

Rev A

100

0.00



Small Fab

Packaging

Memo

0.00

Packaging

Cut as per dwg D2856

*[Signature]* 11/09/28 (30)

110

0.00



QC6- Inspect dimensions to drawing

QC

Memo

0.00

Quality Control

*[Signature]* 11/09/28

(30)

120-

0.00



Identify as per dwg & Stock Location: *[Signature]* 409

Packaging

Memo

0.00

Packaging

*[Signature]* 11-09-28

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 74038**

Page 2

Tuesday, September 20, 2011 3:45:44 PM

Item ID: D2856-400-720

Accept



Setup Start



Revision ID:

Stop



Item Name: Abrasion Strip

Start Date: 9/20/2011 Start Qty: 30.00



Cust Item ID:

Required Date: 9/21/2011 Req'd Qty: 30.00



Customer:

Reference:

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/10/3 *[Signature]*

ME

11-09-28

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Picklist Print

Tuesday, September 20, 2011 3:45:49 PM

Page 1

Work Order ID: 74038



Parent Item: D2856-400-720



Parent Item Name: Abrasion Strip



Start Date: 9/20/2011

Required Date: 9/21/2011

Start Qty: 30.00

Required Qty: 30.00

Comments: IPP Rev:A 10.11.02 as per revA DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2856-400		Manufactured	No			100	f	199.3845	0.6	18			
													
Abrasion Strip													

Location

Loc Qty

Loc Code

ST403

0.3149

68076

0.3149

ST409

199.0696

63735

0.6696

71164

198.4

18

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


**NOTE:** Date & initial all entries



DESIGN <i>CP</i>	DRAWN BY <i>CP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>A</i>	APPROVED <i>A</i>	DRAWING NO. D2856	REV. A SHEET 1 OF 1
DATE 00.11.17		TITLE ABRASION STRIP	SCALE NTS
A	00.11.17	NEW ISSUE	

RELEASED  
00.11.24

## SPECIFICATION CONTROL DRAWING



MATERIAL: OUTDOOR GRADE POLYURETHANE PROTECTIVE TAPE  
3M, P/N 8681 (OR 8681HS)  
THICKNESS: 0.012"

SPECIFICATION: D2856-XXX-YYY ABRASION STRIP

WIDTH  
LENGTH

EG: 1.75"x2.50" ABRASION STRIP = D2856-175-250

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR:-Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries